Ssistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Client ID:

Alt. Client ID: 16016SW-0679

AGENCY INFORMATION

Agency: SWHRA

Address: 1574 White AVE

Henderson, TN

Agency Contact: STANFILL, BUTCH

Address:

Agency Phone: (731) 989-5111

Fax:

Email Address:

Work Phone:

Cell Phone: Email Address:

Company Name & License	Number:		·
Contractor's Signature:			

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-422-4730

Client Name: Client ID: Alt. Client ID: 16016SW-0679 Work Order (Bid Form)

Work Order Name Report Run On: 5/21/2010 DOE Weatherization Assistant

Version 8.5.0 Page 1 of 4

Measures

	Measure 1 Infilt	ration Redctn			Componen	ts		1	nspected
C	omment								
				**************************************	Estimated		as a reserving mineral month system in a ser-	Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Construction Materials/Hardwar e	Seal fireplace trim, Seal kitchen exhaust fan, Master bedroom selal wire in closet Seal pipe under kitchen sink, Laundry room seal pipe behind washer and dryer, Hall bath seal plumbing access for tub	Each	1					
2	Labor	Labor	Hour		7				
3	Construction Materials/Hardwar e								PANGET ALLENSEE ALLEN
C	Other Detail								
ſ									
				Measure	Sub Total:] .	Sub Total:	
	Field Notes:								

Measure 2 DW	VH Pipe Insulation		,,,	Componen	ts			Inspected
			Estimated			Actual		
# Material/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	Labor	Each	1			14.41.41.41.41.41.41.41.41.41.41.41.41.4		
Other Detail				1) (
] [
] [
			Measur	e Sub Total:		•	Sub Total:	
Measure 3 DW	/H Tank Insulation			Componen	!s			Inspected
			Estimated		Actual			
# Material / Labor1 Hot WaterEquipment	Description / Comment DHW Tank Insulation	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
2 Labor	Labor	Each	1					
Other Detail		,	1)		,	<u> </u>	
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:				-			-	

Client Name: Client ID:

Alt. Client ID: 16016SW-0679

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/21/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 4

Measure 4 CO	Monitor is Needed			Componen	ts		^ /	nspected
Comment				Estimateo	ı		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety Items	CO monitor	Each	1	and the state of t			The state of the s	
2 Labor	Labor	Hour	1	Table To Tab				
Other Detail		The state of the s	[1		
]		
	<u></u> j		Measur	e Sub Total:]	Sub Total:	
Field Notes:				<u></u>			L	
Measure 5 Fix C	Other Water Heating Pr	oblem		Componen	ts			nspected
			AND AND A STREET, LAND, LAND,	Estimated			Actual	
# Material/Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Health and Safety Items	Replace water heater with electric 40 gallon ,Plumb pop-off to outside	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
						and the state of		
		1	Measur	e Sub Total:		S	Sub Total:	
Field Notes:								
		Work Or	der Gra	nd Total:		Grand	d Total:	

Client Name: Client ID: Alt. Client ID: 16016SW-0679

Report Run On: 5/21/2010